## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.













FIG. 2









FUSE HOLDER ASSEMSBLY MADHU SUDAN, ET AL. ATTORNEY DOCKET NO. 75IN-126/GEN-0276 10/063,475 DATE FILED: APRIL 26, 2002

2/4





FUSE HOLDER ASSEMSBLY
MADHU SUDAN, ET AL.
ATTORNEY DOCKET NO. 75IN-126/GEN-0276
10/063,475
DATE FILED: APRIL 26, 2002





COPY OF PAPERS ORIGINALLY FILED

